



FACILITY COMPLIANCE INSPECTION REPORT

Division of Waste Management Solid Waste Section

UNIT TYPE:												
Lined MSWLF		LCID		YW		Transfer		Compost		SLAS	X	COUNTY: Lincoln PERMIT NO.: SLAS 55-01 FILE TYPE: COMPLIANCE
Closed MSWLF		HHW		White goods		Incin		T&P		FIRM		
CDFL		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF		

Date of Site Inspection: 3/22/2013

Date of Last Inspection: 8/21/2012

FACILITY NAME AND ADDRESS:

Dennis Hoyle Service
 P.O. Box 84
 Vale, NC 28168

GPS COORDINATES: N: 35.5330 W: -81.42381

FACILITY CONTACT NAME AND PHONE NUMBER:

Name: Dennis Hoyle
 Telephone: (704) 276-2080
 Email address: dhsseptics@gmail.com
 Fax: N/A

FACILITY CONTACT ADDRESS:

N/A

PARTICIPANTS:

Connie Wylie, Tony Gallagher
 Chester Cobb, Dennis Hoyle

STATUS OF PERMIT:

Active

PURPOSE OF SITE VISIT:

Routine

STATUS OF PAST NOTED VIOLATIONS:

N/A

OBSERVED VIOLATIONS

1. N/A

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may also be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

SEE BACK


FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

Page 2 of 2

ADDITIONAL COMMENTS

1. Noted a missing marker at the front right corner of field 1, permitted boundary was determined and a flag posted. Overall it appears that the approved setbacks are being met and the field markers are adequate.
2. **The vegetation needs cut back along the tree line on field 1, overtime the vegetation has encroached onto the required 5' setback.**
3. The required signs are posted and the access road is adequate.
4. The fescue cropstand is well established & no apparent application issues. No odors noted.
5. Cattle were on field 2 as per the nutrient management plan.
6. Site logs were not reviewed at this time.
7. No sign of recent application and no odor noted.

Please contact me if you have any questions or concerns regarding this inspection report.



Connie S. Wylie
Regional Representative

Phone: (910) 433-3352

Sent on:		Email		Hand delivery	X	US Mail		Certified No. <u> </u>
----------	--	-------	--	---------------	----------	---------	--	-------------------------